

Mine Name: Enterprise Mill site

State of UtahDEPARTMENT OF NATURAL RESOURCES Division of Oil, Gas & Mining

MICHAEL R. STYLER Executive Director

JOHN R. BAZA Division Director

Inspection Report Minerals Regulatory Program

December 15, 2009

Reviewed:	R

Permit Number: S/003/0032

	1 01 11110 1 10	MARKOUR. DIOUS	.0052
Operator Name: Bonneville Quarries, Inc.	Inspection Date: October 5, 2009		
Inspector(s): Lynn Kunzler	Time : 3:3	0 pm	
Other Participants: None	Mine Status: Reclaimed		
Elements of Inspection	Evaluated	Comment	Enforcement
 Permits, Revisions, Transfer, Bonds Public Safety (shafts, adits, trash, signs, highwalls) Protection of Drainages / Erosion Control Deleterious Material Roads (maintenance, surfacing, dust control, safety) Reclamation Backfilling/Grading (trenches, pits, roads, highwalls, Soils Revegetation Other 			

Purpose of Inspection:

Routine Inspection while in the area.

Inspection Summary:

Permit fees have not been paid this year, however with the site having been reclaimed, permit fees would be waived.

This site has been reclaimed. All equipment, trailers, vehicles, trash, and rock have been removed from the site. The area has been seeded, as evidence of the seeded species growing. These included crested wheatgrass, slender wheatgrass, sagebrush and rabbit brush (volunteer species included halogeton, Russian thistle, and cheatgrass, but only in minor amounts). Vegetation ground cover of desirable species exceeds the 70% reclamation success standard.

Photos were taken to document site conditions.

Conclusions and Recommendations:

The Division is currently holding a surety (LOC) for \$11,711 for this site. This site is on BLM land. Since this was an off-site mill area, permitted by DOGM only because the BLM required the operator to have a mining permit to validate their mill site claim. On December 8, 2009, the Division received concurrence from the BLM to close this file and release the surety.

Inspector's Signature

Cc: William Bown, Operator

Larry Garahana, BLM (<u>lgarhan@BLM.gov</u>)
O:\M003-BoxElder\S0030032-Enterprise\inspections\Insp-10052009.doc